

## Table ENG-6. - Sanitary Facilities

Lincoln County, West Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
2:							
Nelse	80	Very limited Flooding Depth to saturated zone Too Sandy	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Slope	1.00 1.00 1.00	Very limited Slope Seepage Too Sandy	1.00 1.00 0.50
Chavies	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Grigsby	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Middlebury	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Yeager	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
3A:							
Sensabaugh	80	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Somewhat limited Seepage Gravel content	0.79 0.30
Chagrin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Holly	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lobdell	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Orrville	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

3B:

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
3B: Sensabaugh	80	Very limited Depth to saturated zone Seepage Flooding	1.00 1.00 0.40	Very limited Depth to saturated zone Seepage Flooding	1.00 1.00 0.40	Somewhat limited Seepage Gravel content	0.79 0.30
Grigsby	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lobdell	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Orrville	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Skidmore	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
4: Grigsby	75	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Somewhat limited Seepage	0.50
Chagrin	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Middlebury	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
5: Orrville	73	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Depth to saturated zone	0.96
Lobdell	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Holly	4	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
5: Chagrin	3	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
6: Yeager	90	Very limited Flooding Depth to saturated zone Too Sandy	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Seepage Too Sandy	1.00 0.50
Grigsby	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Nolin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
7: Moshannon	50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not classified	
Chagrin	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Slope Hard to compact	1.00 0.50
Nolin	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Melvin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
8: Lobdell	67	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Seepage Depth to saturated zone	0.50 0.25
Middlebury	17	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Grigsby	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
8: Orrville	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Chagrin	4	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
12: Chagrin	65	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
Nolin	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Grigsby	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Holly	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lobdell	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Orrville	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
13: Nolin	80	Very limited Flooding	1.00	Very limited Flooding	1.00	Not limited	
Chagrin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Grigsby	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lindside	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill			Area Sanitary Landfill	Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
13: Newark	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
14: Holly	85	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
Orrville	6	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Chagrin	3	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Grigsby	3	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Melvin	3	Very limited Depth to saturated zone Slope Flooding	1.00 1.00 0.40	Very limited Slope Depth to saturated zone Flooding	1.00 1.00 0.40	Very limited Slope Depth to saturated zone	1.00 1.00
15: Middlebury	40	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00
Grigsby	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lobdell	14	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	11	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Orrville	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
15: Yeager	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
16A: Cotaco	75	Very limited Depth to saturated zone Flooding	1.00 0.20	Very limited Depth to saturated zone Flooding	1.00 0.20	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
Allegheny	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Monongahela	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
16B: Cotaco	75	Very limited Depth to saturated zone Flooding	1.00 0.20	Very limited Depth to saturated zone Flooding	1.00 0.20	Somewhat limited Depth to saturated zone Too clayey	0.86 0.50
Allegheny	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Monongahela	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
18: Skidmore	80	Very limited Flooding Depth to saturated zone Depth to bedrock	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Somewhat limited Seepage Too Sandy Gravel content	0.50 0.50 0.41
Chagrin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Sensabaugh	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
18: Shelocta	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
21: Kanawha	55	Somewhat limited Flooding	0.40	Somewhat limited Flooding	0.40	Not limited	
Other Soils	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Urban Land	15	Not Rated		Not Rated		Not Rated	
Melvin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
21A: Kanawha	55	Somewhat limited Flooding	0.40	Somewhat limited Flooding	0.40	Not limited	
Gallipolis	30	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Cotaco	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Nelse	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Nolin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
21B: Kanawha	60	Somewhat limited Flooding	0.40	Somewhat limited Flooding	0.40	Not limited	
Elk	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Gallipolis	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
21B: Monongahela	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Cotaco	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Nelse	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
24B: Allegheny	90	Not limited		Not limited		Not limited	
Chavies	10	Very limited Seepage Flooding	1.00 0.40	Very limited Seepage Flooding	1.00 0.40	Somewhat limited Seepage	0.50
24C: Allegheny	90	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
Chavies	10	Very limited Seepage Slope Flooding	1.00 0.63 0.40	Very limited Seepage Slope Flooding	1.00 0.63 0.40	Somewhat limited Slope Seepage	0.63 0.50
27C: Latham	55	Very limited Depth to saturated zone Depth to bedrock Too acid	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to bedrock Slope	1.00 1.00 0.63	Very limited Depth to bedrock Hard to compact Depth to saturated zone	1.00 1.00 0.71
Gilpin	30	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Slope Gravel content	1.00 0.63 0.03
Cavode	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
27D: Latham	40	Very limited Depth to saturated zone Slope Depth to bedrock	1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00



**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
27D: Gilpin	30	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Cavode	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Coolville	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lily	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Upshur	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Wharton	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
29D: Lily	40	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.50
Marrowbone	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Gilpin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Matewan	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Muskingum	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Ramsey	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill			Area Sanitary Landfill			Daily Cover for Landfill		
		Rating Class and Limiting Features	Value		Rating Class and Limiting Features	Value		Rating Class and Limiting Features	Value	
29D: Udorthents	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact	1.00 0.50	
29E: Lily	75	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50		Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00		Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.50	
Marrowbone	15	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact	1.00 0.50	
Matewan	10	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact	1.00 0.50	
29F: Sharpcrest	50	Very limited Slope Depth to bedrock	1.00 1.00		Very limited Slope Seepage Depth to bedrock	1.00 1.00 0.61		Very limited Slope Depth to bedrock Seepage	1.00 0.61 0.50	
Hazleton	20	Very limited Slope Depth to bedrock Content of large stones	1.00 1.00 0.02		Very limited Slope Seepage Depth to bedrock	1.00 1.00 0.77		Very limited Slope Seepage Depth to bedrock	1.00 1.00 0.77	
Marrowbone	15	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact	1.00 0.50	
Gilpin	10	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact	1.00 0.50	
Matewan	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact	1.00 0.50	
31C: Gilpin	55	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63		Very limited Depth to bedrock Slope	1.00 0.63		Very limited Depth to bedrock Slope Gravel content	1.00 0.63 0.03	

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
31C: Upshur	25	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63	Somewhat limited Slope Depth to bedrock	0.63 0.61	Very limited Too clayey Hard to compact Slope	1.00 1.00 0.63
Latham	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
31D: Gilpin	55	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Upshur	25	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.61	Very limited Slope Too clayey Hard to compact	1.00 1.00 1.00
Latham	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
31E: Gilpin	50	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Other Soils	30	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Upshur	20	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.61	Very limited Slope Too clayey Hard to compact	1.00 1.00 1.00
31F:							

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
31F: Gilpin	50	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Upshur	25	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 0.61	Very limited Slope Too clayey Hard to compact	1.00 1.00 1.00
Rayne	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Peabody	8	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
32E: Gilpin	45	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Wharton	30	Very limited Depth to saturated zone Slope Depth to bedrock	1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 0.71	Very limited Slope Depth to bedrock Depth to saturated zone	1.00 0.71 0.71
Blairton	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Marrowbone	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Matewan	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Rayne	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

32F:

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
32F: Gilpin	60	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Matewan	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Muskingum	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Peabody	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Upshur	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	4	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
33C:							
33D: Gilpin	60	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Muskingum	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Wharton	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Latham	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Lily	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
33D: Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Rayne	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
33E: Gilpin	70	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Marrowbone	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Matewan	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Muskingum	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
34E: Gilpin	30	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Gravel content	1.00 1.00 0.03
Matewan	20	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Marrowbone	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Wharton	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
34E: Muskingum	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Ramsey	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
34F: Rayne	53	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 0.61	Very limited Slope Depth to bedrock Too clayey	1.00 0.61 0.50
Matewan	22	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Gilpin	17	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Content of large stones	1.00 1.00 1.00
Hazleton	8	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Gravel content	1.00 1.00 0.02
35F: Clymer	40	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 0.18	Very limited Slope Too clayey Depth to bedrock	1.00 0.50 0.18
Matewan	35	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Other Soils	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
37E: Gilpin	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
37E: Latham	20	Very limited Depth to saturated zone Slope Depth to bedrock	1.00  1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00  1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
Matewan	20	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Upshur	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Rayne	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Wharton	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
38F: Higsplint	35	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Gravel content	1.00 0.50 0.27
Matewan	25	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Cloverlick	15	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Content of large stones	1.00 0.50 0.10
Other Soils	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Shelocta	7	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50



**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
38F: Feds creek	6	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Gilpin	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
39F: Berks	45	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.50
Shelocta	35	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 0.61	Very limited Slope Depth to bedrock Too clayey	1.00 0.61 0.50
Cloverlick	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Highsplint	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Matewan	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Too clayey Seepage	1.00 0.50 0.22
40D: Dormont	45	Very limited Depth to saturated zone Slope Depth to bedrock	1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 0.13	Very limited Slope Depth to saturated zone Too clayey	1.00 0.71 0.50
Latham	35	Very limited Depth to saturated zone Slope Depth to bedrock	1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
40D: Other Soils	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
40E: Dormont	50	Very limited Depth to saturated zone Slope Depth to bedrock	1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 0.13	Very limited Slope Depth to saturated zone Too clayey	1.00 0.71 0.50
Latham	25	Very limited Depth to saturated zone Slope Depth to bedrock	1.00 1.00 1.00	Very limited Slope Depth to saturated zone Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
Other Soils	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
42D: Beech	75	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Depth to saturated zone Too clayey	1.00 0.71 0.50
Shelocta	15	Very limited Slope Content of large stones Too clayey	1.00 0.79 0.50	Very limited Slope	1.00	Very limited Slope Content of large stones Too clayey	1.00 0.79 0.50
Other Soils	5	Very limited Slope Content of large stones Too clayey	1.00 0.79 0.50	Very limited Slope	1.00	Very limited Slope Content of large stones Too clayey	1.00 0.79 0.50
Vandalia	5	Very limited Slope Content of large stones Too clayey	1.00 0.79 0.50	Very limited Slope	1.00	Very limited Slope Content of large stones Too clayey	1.00 0.79 0.50
42E:							

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
42E: Beech	50	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Depth to saturated zone Too clayey	1.00 0.71  0.50
Vandalia	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Shelocta	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
43E: Pineville	60	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
Cloverlick	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Highsplint	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Beech	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
45C: Vandalia	75	Very limited Depth to saturated zone Too clayey Slope	1.00 1.00 0.63	Very limited Depth to saturated zone Slope	1.00 0.63	Very limited Too clayey Hard to compact Slope	1.00 1.00 0.63
Shelocta	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
45C: Beech	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
45D: Vandalia	70	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 1.00	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Too clayey Hard to compact	1.00 1.00 1.00
Shelocta	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Beech	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
45E: Vandalia	50	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 1.00	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Too clayey Hard to compact	1.00 1.00 1.00
Beech	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Shelocta	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
47: Guyan	85	Very limited Depth to saturated zone Too clayey Flooding	1.00 0.50 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Very limited Depth to saturated zone Too clayey	1.00 0.50
Cotaco	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Monongahela	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
47: Purdy	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
71B: Kaymine	35	Very limited Seepage Content of large stones	1.00 0.62	Very limited Seepage	1.00	Somewhat limited Content of large stones Seepage Gravel content	0.62 0.50 0.42
Fiveblock	25	Very limited Seepage Content of large stones	1.00 0.52	Very limited Seepage	1.00	Very limited Seepage Content of large stones Gravel content	1.00 0.52 0.19
Sewell	17	Very limited Seepage	1.00	Not limited		Somewhat limited Hard to compact	0.50
Cedarcreek	15	Very limited Seepage	1.00	Not limited		Somewhat limited Hard to compact	0.50
Fairpoint	5	Very limited Seepage	1.00	Not limited		Somewhat limited Hard to compact	0.50
Other Soils	3	Very limited Seepage	1.00	Not limited		Somewhat limited Hard to compact	0.50
71F: Kaymine	40	Very limited Slope Seepage Content of large stones	1.00 1.00 0.62	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.62 0.50
Fiveblock	25	Very limited Slope Seepage Content of large stones	1.00 1.00 0.52	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Content of large stones	1.00 1.00 0.52
Sewell	17	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Fairpoint	13	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
71F: Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
74F: Kaymine	30	Very limited Slope Seepage Content of large stones	1.00 1.00 0.62	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.62 0.50
Cedarcreek	25	Very limited Slope Seepage Content of large stones	1.00 1.00 0.95	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.95 0.50
Matewan	20	Very limited Slope Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 1.00
Fairpoint	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Fiveblock	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Other Soils	5	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
75F: Cedarcreek	70	Very limited Slope Seepage Content of large stones	1.00 1.00 0.95	Very limited Slope Seepage	1.00 1.00	Very limited Slope Content of large stones Seepage	1.00 0.95 0.50
Other Soils	20	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Rock Outcrop	10	Not Rated		Not Rated		Not Rated	

121:

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill			Area Sanitary Landfill			Daily Cover for Landfill
		Rating Class and Limiting Features	Value		Rating Class and Limiting Features	Value		Rating Class and Limiting Features
121: Lindside	85	Very limited Flooding Depth to saturated zone	1.00 1.00		Very limited Flooding Depth to saturated zone	1.00 1.00		Somewhat limited Depth to saturated zone
Melvin	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
Newark	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
Senecaville	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
122: Senecaville	90	Very limited Flooding Depth to saturated zone	1.00 1.00		Very limited Flooding Depth to saturated zone	1.00 1.00		Somewhat limited Depth to saturated zone
Lindside	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
Melvin	5	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
124B: Cotaco	40	Very limited Depth to saturated zone Flooding	1.00 0.40		Very limited Depth to saturated zone Flooding	1.00 0.40		Somewhat limited Depth to saturated zone
Other Soils	25	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
Urban Land	25	Not limited			Not limited			Not limited
Allegheny	10	Very limited Slope Seepage	1.00 1.00		Very limited Slope	1.00		Very limited Slope Hard to compact
124C:								

**Table ENG-6. - Sanitary Facilities - Continued**

Lincoln County, West Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill	Value	Area Sanitary Landfill	Value	Daily Cover for Landfill	Value
		Rating Class and Limiting Features		Rating Class and Limiting Features		Rating Class and Limiting Features	
124C: Cotaco	40	Very limited Depth to saturated zone Slope Flooding	1.00 0.63 0.40	Very limited Depth to saturated zone Slope Flooding	1.00 0.63 0.40	Somewhat limited Depth to saturated zone Slope	0.86 0.63
Other Soils	25	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
Urban Land	25	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63	Somewhat limited Slope	0.63
Allegheny	10	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
180: Urban Land	85	Not Rated		Not Rated		Not Rated	
Other Soils	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
181: Udorthents	50	Very limited Seepage	1.00	Not limited		Very limited Hard to compact	1.00
Urban Land	25	Not Rated		Not Rated		Not Rated	
M: Udorthents	85	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 1.00
Other Soils	15	Very limited Slope Seepage	1.00 1.00	Very limited Slope	1.00	Very limited Slope Hard to compact	1.00 0.50
W:							